



# CAMPRO CPV-1050B 4 Plus 1 HIGH PERFORMANCE VERTICAL MACHINING CENTER

## **MACHINE FEATURES**

- •Constructed with high quality mechanite cast iron and heat treated to relieve stress thereby assuring maximum rigidity and accuracy.
- •Box ways on all 3 axes greatly upgrades stability and dampening capability.

•Automatic lubrication unit with intelligent pressure failure detection function provides reliable supply for saving cost and for environmental protection.

•Oil-coolant separation design which meets the environment protection requirements allows centralized collection for all way oil.

## **STANDARD FEATURES:**

- \* Fanuc Oi-MF PLUS Control
- \* AICC2+ Contour Control
- \* 12,000 RPM Spindle (Belt Drive)
- \* Powerful 25 HP high torque spindle motor
- \* Cartridge Spindle Design
- \* CAT40 Big Plus Spindle
- \* 290 PSI Through Spindle Coolant
- \* Spindle Air Blow
- \* Rigid tapping

## STANDARD FEATURES (CONT'D):

- \* Custom Macro B (User Definable)
- \* Twin Arm 24 Tool ATC
- \* Portable Manual pulse generator
- \* Massive One-piece Meehanite cast iron bed
- \* Chip Auger
- \* 4<sup>th</sup> Axis Prep
- \* Low friction Turcite mating way surfaces
- \* Double Anchored, Pre-tensioned Ballscrews
- \* Fast 1,181 IPM Rapid Traverse rate
- \* Full enclosure splash guard
- \* Flood coolant with large coolant tank
- \* Work light
- \* Operator call lamp (red, yellow, green)
- \* Spindle load meter
- \* Assembly and operation tools
- \* Auto Power Off
- \* Heat exchanger for Electrical Cabinet
- \* Instruction manual, parts list, and electrical diagram
- \* Fanuc operator and maintenance manuals
- \* WARRANTY-MACHINE: One-Year
- \* WARRANTY-CONTROL: Two-Years

## **SPECIFICATIONS**

## CAPACITY:

X axis travel	41.3"
Y axis travel	20.9"
Z axis travel	30.7"
Table loading area	41.3" x 20.9"
Allowable table load	2200 pounds
5	

## **TRUNNION TABLE**

Table diameter	12.6"
Maximum Workpiece Diameter	15.75"
Spindle nose to trunnion table top	20.6"
Maximum Workpiece Weight	220 pounds

#### SPINDLE:

Spindle nose to machine table top Spindle Bearing Diameter Column to spindle center Spindle taper Spindle speed A.C. spindle motor Spindle torque Spindle Driving Method 3.9" – 34.6" 2.8" 23.2" CAT 40 Big Plus 12,000 RPM 25 HP 132 ft-lbs. Belt Drive

## **SPECIFICATIONS (Continued)**

## **AUTOMATIC TOOL CHANGER:**

АТС Туре
Number of Tools
Tool Shank
Max. Tool Dia.
Max tool Diameter (No Adjacent Tool)
Max. Tool Length
Max. Tool Weight

### **MOTION:**

X and Y axis rapid traverse rate Z axis rapid traverse rate Cutting feed rate Slide Type Least command increment Roundness accuracy Bi-Directional Accuracy Bi-Directional Repeatability

#### **GENERAL**:

Floor Space Required (W x D X H) Machine Weight Standard Power Source Requirement - Fanuc Power Capacity Air Source Requirement Twin Arm Type 24 CAT 40 3.1" 5.9" 9.8" 15.4 lbs. Random Bi-Directional

1,181 IPM 1,181 IPM 393 IPM Box Ways .001mm, < .00020" < .00020" < .00030"

125" x 96" X 120" 14,770 lbs. 205-235 Volts / 3 Phase/60HZ 53 Amps Minimum 85 – 115 PSI

### **CONSTRUCTION:**

- Balanced 12,000 RPM Spindle with 6000 BTU spindle oil cooler for High Speed Machining.
- Hardened and Ground C3 Double Nut Ballscrews (Ø40 mm) are pre-tensioned to minimize backlash, provide high precision movement, and reduce heat deformation on all axes.
- All solid ways are coated with high grade Turcite-B. Hardened and ground slideways give an extra 40% wear resistance.
- 2 Solid Box Ways are on a one-piece base instead of two supporting ways connected to the main base, which provides more rigidity under heavy machining.
- Main frame is made of Meehanite casting for superior rigidity

## **BED, COLUMN, AND SADDLE:**

The bed is a rigid one-piece casting with heavy ribbing to prevent deformation during heavy cutting. Fine grain Meehanite cast iron is used for its excellent dampening characteristics. Extra wide boxways provide excellent support for the saddle, regardless of the load distribution on the table. The table is fully supported by the saddle in all positions. There is no table overhang. The rigid box type column casting is heavily ribbed to prevent twisting or distortion.

## **CONSTRUCTION (Continued)**

### SPINDLE, HEADSTOCK, AND COLUMN

The high speed, 12,000 RPM, 40 taper spindle is a true cartridge type unit supported by precision class bearings that are permanently grease lubricated. The spindle is driven by a high torque 25 HP A.C. motor delivering an impressive 132 ft/lbs. Power is transferred through a heavy-duty cogged drive belt eliminating slippage, promoting thermal stability, and minimizing vibration. An encoder is attached to the spindle to allow rigid tapping.

#### **GUIDEWAYS**

Wide Box ways are used for unsurpassed long-term rigidity and accuracy. Each guideway is induction hardened and precision ground. Turcite is bonded to the mating way surfaces and then hand scraped to ensure perfect fit and tolerances. The Turcite resin with forced way lubrication provides a low friction surface and virtually eliminates guideway wear. All guideways are fully protected from chips and damage.

#### OIL JACKET SPINDLE CHILLER (STANDARD)

Machine accuracy is maintained by using a refrigeration system that circulates cooled oil around the spindle reducing the thermal effects of any heat generated.

#### AUTOMATIC TOOL CHANGER

The high quality 24-position tool changer uses a fast random bi-directional twin arm with 2.5 second tool-to-tool change time, and 6 seconds chip to chip.

#### **BALL SCREWS AND AXIS DRIVES**

Each axis is driven by a high precision double-nut ballscrew. The ballscrews are centered between the guideways. The ballscrews are supported on both ends by angular contact thrust bearings. This <u>double</u> <u>anchored pretension</u> design provides outstanding positioning repeatability with virtually no thermal growth. All axes have large diameter 40 mm ball screws that are connected directly to oversize AC servo drive motors without gears or belts, to eliminate backlash. Each axis has a <u>flexible coupling</u> to protect the ball screw in the event of a sudden impact. These couplings can be quickly reset.

#### PORTABLE MANUAL PULSE GENERATOR

The hand held "<u>Manual Pulse Generator</u>" lets each axis move in increments of 0.0001", 0.0010" or 0.0100" making fixture or part alignment quick and easy. The 10-foot cord gives full access to the machine.

#### 290 PSI (20 BAR) THROUGH-SPINDLE-COOLANT SYSTEM

A dedicated **<u>290-PSI</u>** positive displacement pump delivers the coolant directly to the tool tip. The immediate benefit is more aggressive feeds and speeds can be maintained throughout the cutting process. There is also no need to stop and adjust coolant nozzles increasing the in-cut time and operator safety. Protecting the spindle and the vital rotary union from contamination is a canister filter with a replaceable **<u>10-micron</u>** element.

#### FULLY ENCLOSED GUARDING


The fully enclosed guarding, including cut-out for filter mist, is made of heavy gauge sheet metal to contain both chips, coolant and coolant mist. The large dual sliding doors open to provide unrestricted overhead access for ease of lifting heavy fixtures or work pieces.

## CHIP DISPOSAL AND COOLANT SYSTEM

High volume coolant system washes chips down into the front of sheet metal enclosure for chip auger evacuation and provides flood coolant through adjustable head mounted nozzles along with four flushing nozzles mounted directly to spindle nose.







## **Control Specifications - Fanuc 0i-MF PLUS**

10.4" Color LCD Screen MANUAL GUIDE i 2 MB Program Storage Size 1000 Part Program Storage AICC2+ Fine Surface Machining: 200 Block Look-Ahead Smooth Tolerance Control -Jerk Control Machining Quality Level Adjustment Machine Condition Selecting (Programmable, G05.1 R1-10 sets accuracy level) USB Reader **RS-232** Interface PCMCIA Memory Card **Embedded Ethernet Back Ground Editing** Extended Part Program Editing (Copy, Move, Change of NC Program) Set-up Guidance Dynamic Graphic Display Skip Signal Multi-Step Skip Signal Multi-language Display Color graphics Simultaneous Controlled Axis Least input Increment on X, Y, and Z is .001 mm Least command increment on X, Y, and Z is .001mm Inch/Metric Conversion (G20/G21) Interlock on All Axes Machine Lock on All Axes **Emergency Stop** Stored Stroke Check 1, 2, 3, Mirror Image **Backlash Compensation** Unexpected disturbance torque detection Stored pitch compensation Automatic Operation (Memory) **MDI** Operation Search Function (Sequence, Program) Program restart Dry Run Single Block **Buffer Register** Manual Handle Interrupt Manual Jog Feed (Rapid, Jog, Handle) Manual Handle Feed Rate (x1, x10, x100) Feed Command (F Code Feed Rate Direct Command) Feed rate Override 0-200% (10% Unit) Jog feed 0-5,000 mm/min (197 ipm) Rapid traverse override (F0, F25%, F50%, F100%) **Override Cancel** Rapid Traverse Bell-Shaped Acceleration/Deceleration Block Skip Exact Stop Mode / Exact Stop (G61/G09) Dwell (G04) Helical Interpolation Threading/Synchronous Feed Manual Reference Point Return 1<sup>st</sup> Reference Point Return G28 **Reference Point Return Check G27** 

## Control Specifications - Fanuc 0i-MF PLUS CONT'D:

2<sup>nd</sup> Reference Point Return G30 3<sup>rd</sup> and 4<sup>th</sup> Reference Point Return Program stop, optional stop, end of program M00, M01, M02, M30 Tape Code EIA RS-244/ISO 840 (Automatic Recognition) Optional Block Skip (9 ea.) Maximum Programmable Dimensions +/- 9999.9999" (+/- 8 digits) Absolute and Incremental Command G90/G91 **Decimal Point Input** Plane Selection G17 G18 G19 Work Coordinate System Setting (G52 – G59) Work Coordinate Preset Additional Work Coordinate System 48 pairs Manual Absolute "On" fixed Programmable Data Input G10 Sub Program Call 4 Levels of Nesting Custom Macro #100 to #199 Addition to Custom Macro Common Variables #500 to #999 Circular Interpolation by radius R Canned Cycle (G73, G74, G76, G80 ~ G89) Optional Chamfering / Corner R Skip Function (G31) Automatic Coordinate System Setting **Coordinate System Rotation** Programmable Mirror Image Single direction positioning (G60) External Data Input (Tool Offset, message, machine zero-point shift) Cylindrical interpolation A1 Advance Preview Control (G5.1) Polar Coordinate Command Miscellaneous Function (M3 digits) Miscellaneous Function Lock Spindle Speed Command (S5 Digits, binary output) Spindle Speed Override (50% ~ 120%) 10% Unit **Rigid Tapping** Cutter Compensation C (G40-G42) **Tool Length Measurement** Tool Length Compensation (G43, G44, G49) Tool Offset Amount (+/- 6 Digits) Tool Offset Pairs (400 Pairs) **Tool Life Management** Memory Lock **Back Ground Editing** Extended Part Program Editing (Copy, Moye, Change of NC Program) History Display of Alarm and Operator Message Help Function Run Hour / Parts Count Display Actual Cutting Feed Rate Display Spindle / Servo Setting Screen Erase CRT Screen Display (Screen Saver) **Bi-Direction Pitch Error Compensation Tool Management Function** Protection of Data at 8-Levels Tool Monitoring Function (HWTM – Built-on Fanuc Type) Fanuc Manual Guide i conversational programming Alpha i AC digital servo system with 1,000,000 pulse encoders Automatic Acceleration / deceleration with Bell Shaped rapid acc / dec 4 axes simultaneous control std. Scaling Custom Macro B High speed skip signal